## PEGEIVED CENTRAL PAX BENTER

JUL 09 2008

## **REMARKS**

Claims 1-11 and 22- 24 remain before the Examiner for reconsideration. Claims 1-3, 5, 8, 14, 22 and 24 have been amended. The amendments have been made to place the Application in better condition for allowance. Specifically, the syringe body has been amended to read "tubular body." No new matter has been added, and support for the amendments is found in the specification as originally filed.

## REJECTIONS UNDER 35 USC 102(b)

Claim 14 stands rejected under 35 USC 102(b) as being anticipated by Hitchins et al. This rejection should be withdrawn in view of the remarks and amendments made herein.

Claim 14 is directed to a syringe and has been amended to include "at least one attachment member disposed on the rearward end of the tubular body; and at least one rotation member comprising a recess formed in the rearward end of the tubular body for releasably retaining a corresponding member of the syringe retaining mechanism of the injector."

The Office Action alleges that Hitchins teaches a syringe comprising a body (50'), a plunger (15), an attachment member (62') at the rearward end of the body; and a rotation member comprising a recess (just distal of 170') formed in the body for retaining a corresponding mechanism on the injector.

However, Hitchins does not disclose the novel features of Applicants' invention. The syringe of Hitchins includes mounting flanges 170, 170' with a space located distally. Thus, the space if located not reaward but foorward of the flanges 170, 170', and this is different than Applicant's invention in which "a recess [is] formed in the rearward end of the tubular body." Therefore, in Hitchins the space it is the flanges 170, 170' that are disposed at a reaward position. Accordingly, Hitchins does not disclose Applicants' invention of Claim 14. Reconsideration of the Examiner's rejection is requested.

## **REJECTIONS UNDER 35 USC 103**

Claims 1-11 and 22-24 stand rejected under 35 USC 103(a) as being obvious over

Reilly in view of Hitchins. The rejection should be withdrawn in view of the remarks and amendments made herein.

Claim 1 is directed to a syringe and has been amended to include, "at least one attchment member disposed on the rear end or front end of the tubular body..." and "at least one encoding ring disposed on at least on a portion of the tubular body and operable to provide syringe information to the injector."

Applicants' invnetion includes this novel structure as shown in Figure 126. "Syringe 4612 includes a cylindrical body 4630 with a tapering conical portion 4632 at a front end 4634. Conical portion 4632 is integrally connected to a discharge end 4636." (Application, Page 56, paragraph 3).

The Office Action alleges that Reilly teaches an attachment member 126 and a rotation member comprising a recess 120 formed in the body, and that the attachment member is an annular risge 126 which is also a proejction or tab member in Fig. 10. Further, the Office Action alleges that regarding claims 10 and 11, the attachment member could be moved in either an axial or vertical direction.

However, Reilly does not teach or suggest Applicants' invention. Reilly is directed to:

[a] fluid injector indicated generally at 110 includes a pressure jacket 112 with a plurality of locking fingers 114 for engaging a syringe 116, shown in an open position in FIG. 10 and a closed position in FIG. 11. Pressure jacket 112 is connected at its rear end 132 to injector head 20 by any suitable means, such as a threaded connection (not shown). Syringe 116 has a cylindrical body 118 having a front end 120 and an open rear end 122. The front end 120 of syringe 116 is tapered and connected to a neck 124. A disk shaped drip flange 126 is formed around the neck 124. (Col. 5, lines 48-57, Emphasis Added)

Thus, the drip flange 126 is not an attachment member because structurally it does not provide any attachment between the body and the pressure jacket 112 that retains the syringe. Further, drip flange 126 is not releasably retained by the syringe retaining mechanism, rather drip flange 126 remains <u>outside of the syringe jacket 126</u>. In fact, in Reilly the "front end 142 of the locking ring 140 is a distal annulus extending radially inwardly to form an open orifice 144 which permits the syringe body 118 to be inserted into pressure jacket 112, but <u>does not permit the drip flange 126 to be inserted into pressure jacket 112</u>. FIG. 10 shows that the front interior surface of the front end 142 is sloped to engage locking fingers 114 when in a closed position, as shown in FIG. 11 and more fully described below."

(Col. 5, lines 11-19, *Emphasis Added*.) Also, the drip flange 126 of Reilly is **not** disposed on the the body of the syringe, but is disposed on the neck 124 which is distally located from a tapered front end 120 and, thus from the body 118. Therefore, Reilly does not disclose "at least one attachment member disposed on the rear end or the front end of the tubular body" as claimed in Applicants' invention of Claim 1.

The Officie Action also alleges that Hitchins teaches a syringe body (50) for use with an injector (20) where the syringe includes coding (190, 192), and that it would have been obvious to one of ordinary skill in the art at the time the invention was made to use the known technique of an encoding ring with the device of Reilly in order to provide an indication of medication contained with the syringe or the size of the syringe.

However, there is not a teaching or suggest of Applicants' invention of <u>at least one</u> encoding ring formed in at least on a portion of the tubular body and operable to provide syringe information to the injector. Recesses or depressions 190, 192 are formed in the outer most flanges 170, 170'. The recesses 190, 192 are used to activate a mechanical spring activate switch. (Col. 10, line 66 – Col. 11, line 6). Thus, these depressions 10, 192 are not the ring that is formed in the tubular body. Therefore, Hitchins fails to remedy the deficiencies of Reilly. Reconsideration of Claim 1 is requested.

Regarding Claim 3, Reilly does not teach or suggest Claim 3 because attachment member 126 is not a projection that is adapted to engage corresponding members of the syringe retaining mechanism to enable release of the syringe from the injector thought rotational movement. (see Col. 6, lines 20-37),

Regarding Claim 2, Reilly does not teach or suggest that the at least one attachment member comprises an annular ridge disposed on the tubular body. Rather the attachment member is forward of the front end 120 of the syringe which is connected to a neck 124. And, the drip flange 126 is formed around the neck 124 (Col. 5, lines 54-57)

Regarding Claim 4, Reilly does not teach or suggest the at least one attachment member that comprises one or more tab members because the drip flange 126 is one continuous disk shaped flange that is formed around the neck.

Regarding Claim 5, Reilly does not teach or suggest the tab members that comprise a first tab end attached to the body and a second tab end adapted to engage the syringe retaining mechanism of the injector. Rather, as discussed above drip flange 126 is

connected and formed around the neck and does not attach to any part fo the syinge retaining mechanism.

Regarding Claim 6, Reilly does not teach or suggest tab members that are resilient members. In fact, Reilly teaches a drip flange 126 that is fixed around the neck 124. Further, Hitchins does not remedy any of the deficincies of Reilly, and therefore Claims 2-11 and 22-24 are not taught or disclosed by either Reilly or Hitchins, alone or in combination.

Further, Claims 2-11 and 22-24 depend from Claim 1, which as discussed is believed to be allowable. Accordingly, Claims 2-11 and 22-24 are also believed to be allowable. Reconsideration of the rejections of Claims 2-11 and 22-24 is requested.

Dated: July 9, 2008

In view of the above remarks, the Applicants respectfully request that the Examiner withdraw the rejections of the claims, indicate the allowability of the claims and arrange for an official Notice of Allowance to be issued in due course.

Respectfully submitted,

/Jill Denesvich/

Jill Denesvich / Reg. No. 52,810

Medrad, Inc.
One Medrad Drive
Indianola, PA 15051

Telephone: (412) 767-2400